Due to the variance in the size of the 4^{th} gear that slides over the quill, prior to installation ensure that the gear slides over the quill easily.

