

Models w/ separate heater core must have the Roof Panel Spacer removed.

- 1. Remove OE Weatherstrip #R52149
- 2. Replace with OE Filter #R50481



